

September 28, 2018

Office of Enforcement, Compliance & Environmental Justice (8ENF-AT) U. S. Environmental Protection Agency Region VIII 1595 Wynkoop Street Denver, Colorado 80202-1129

RECEIVED

OCT 2 - 2018

Re:

Hunt Oil Company

NSPS OOOOa Initial Annual Report

Office Jement Compliance & Environmental Justice

This serves as the initial annual report for Hunt Oil Company in accordance with 40 CFR §60.5420a for the compliance period. The affected facilities are specified in the attached spreadsheet.

I certify that I am the Responsible Official for the affected facilities. Based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate and complete.

Please do not hesitate to contact me at (214) 978-8941 or Jordan Brundige at (214) 978-8265 if you have any questions or require further information regarding this matter.



Attachment

Well Affected Facilities (well completion operations with hydraulic fracturing after November 30, 2016)

1	Reporting Period:	First Initial Report - 11/30/20	16 - K/28/2018

Facility/Well Name	US Well (D	lat/long (decimals to 5 decimals of a degree)*		Well Affected Facilities Using a Digital Photo in licu of Records Required by \$60.5420a(c)(1)(i) through (iv) (Blename.pdf)	Onset of Flowback (Date and Time)	direct flowback to	Each occurrence of returning to initial flowback (Date and Time)	When flowback equipment was permanastly disconnected, or the startup of Production. (Date and Time)	Duration of Flowback(bours)	Disposition of Flowback	Duration of Combustion (hours)	Duration of venting (bours)	Reasons for vestring  NA  NA  NA	Deviations
WEFLEN 2-27H	3306102147	(b) (9)	Take HWY 2 to Palermo then go South on 74th for 14 miles, turn Right on 49th.	NA	NA.	NA.	NA.	7/20/2018 8:00	0	N/A	0	0	NA.	None
AUSTIN 154-90-27-22H-1	3306103282		Hwy US-2 from Ross, take a left on 74th Avenue NW, follow approximately 17 miles to 49th St NW, turn right and follow approximately 2 miles, location will be on the right.	NA NA	NA	NA.	NA.	7/25/2018 8:00	ď	N/A	0	0	NA NA	None
AUSTIN 154-90-27-22H-2	3306104211		Hwy US-2 from Ross, take a left on 74th Avenue NW, follow approximately 17 miles to 49th St NW, turn right and follow approximately 2 miles, location will be on the right.	NA.	6/15/2018 11:00	6/15/2018 11:00	NA.	7/28/2018 8:00	0.25	Routed to collection system/production battery	0.	o	NA NA	None
NICHOLS 156-90-10-15H-3	3306103401		Take Hwy 2 to Palermo exit go North 1/4 mile turn left on lease road. Location ahead 1/4 mile.	NA NA	8/27/2018 7:00AM	8/27/2018 7:00AM	NA	8/28/2018 6:00	11	Routed to collection system/production battery	0	0	NA NA	None
NICHOLS 156-90-10-15H-4	3306104220		Take Hwy 2 to Palermo exit go North 1/4 mile turn left on lease road. Location shead 1/4 mile.	NA.	8/15/2018 18:00	8/15/2018 18:00	NA.	8/16/2018 6:00	12	Routed to collection system/production battery	0	0	NA	None

Reporting Portial:	Ford Install Region - November 30, 2016 - 4/24/2018																OCI	Compressor Station Affected Facility Only							
Feelity Name	Date of Survey	Survey Steple These	Survey East Time	Name of Surveyor	Ambient Temperature During Survey	Sky Condition During Survey	Machine Wind Speed Desting Survey (MPSI)	Manhoring Servences Unit	Declation From Monitoring Plan	Type of Compound for which Pagette Euclidean Detected	Number of Each Compound Type for which Fugitive Enclusions Detected	Type of Component Not Repaired as Required in \$60.5397a(k)	Sumpler of back Component Type Nor Repaired as Required to § 60.5397a(k)	Type of Difficult to Manker Components Mankered	Number of Each Difficult in Months Component Type Months vid	Type of Unach in Manther Compound Manthered	Number of Easts Laude to Menter Companied Type Manhard	Date of Successful Repair of Englishe Englishme Competent	Type of Component Placed on Delay of Repair	Number of Earth Component Type Pleased on Only of Supelo	Exploration for Delay of Sepair	Type of Instrument Limit to Reservey Repaired Components Not Repaired During Original Survey	Training and Experiment of Surveyor	Was a making more wated under ( 40.5397 agg/cl)?	If a modificing survey was waited the valuedor muscles that mobile the sparticity modificing ported which the manifesting movey to market.
Wefien 1-27 CTB	9/11/2018	231	852	Ber Hamilton	40	Overcass	· a	+LIR GF321	None	None	N/A	None	N/A	NA)	N/A	- NA	NA .	NA	NA.	NA .	NA.	NA.	frained Thermographer. Has completed OGI certification expires 1/1/2022	No	n/A
Nichols 10-15 CTB	9/21/2018	10-06	1107	Bar Hamiton	40	Partly Cloudy	*	FUR GF322	None	Neve	NA	None	MA	NA	N/A	164	NA NA	NA.	NA	u	96	NA .	Trained Thermigrapher. Has completed OGI certification expires. 1/5/2022	No	N/A